

CASPIR Aircraft Accident Cards

Serial: FE278

Title: North American Harvard Mk. IIB serial:FE278 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-18. Harvard II s/n FE278. This accident involved 1 person. Chowne HW

Keywords: RAFHarvard II,FE278,41 SFTS,41 Service Flying Training School,R1 Halbritte,1943-January-18,ChowneRCAF L20

Created: 1943-01-18

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE278>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

Precautionary landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Failed to lower undercarriage and made belly landing.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~34. Wheels up landing.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed and action under T.C.I's. Serial 3/19.

⑦ *Other*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot was careless in assuming U/C to be down, because the horn did not sound, further failed to check indicators and warning lights.~~

③②

U/C Drill - in air

RECORDED BY

DATE

INDEXED BY

DATE