

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62
PILOT		OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																							
CAUSES OF ACCIDENTS																																																													
UNIT		COM.		PLACE										DATE		TIME																																													
37 S.F.T.S.		# 4		Main Aerodrome										25-1-43		1045																																													
Calgary, Alberta														H.Q. FILE		1300-AJ795																																													
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																																																	
Harvard II		AJ795		C 2		x						x																																																	
NAME		RANK		No.		DUTY		INJURIES				SERIOUS																																																	
Mathew, T.		P/O		522927		FI		Nil				FATAL INJURY																																																	
Metz, L.G.		LAC		1395413		PP		Nil																																																					
												CARD SERIAL No.																																																	
												✓																																																	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																	
Harvard II AJ795		Slight										INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																											
Wasp 4645/9257 Nil														DUAL SOLO		DUAL SOLO																																													
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE																																															
A 15		25-1																																																											
NATURE OF ACCIDENT																																																													

CAUSES
 MISCELLANEOUS
 STAGE OF FLIGHT

HAND Q
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND/TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 INJURY
 3RD.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Dual instructional flight.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 26 Jan./43

INVESTIGATING OFFICER D-14

Taxied into stationary tractor on edge of runway.

COMPOSITION:

P.O. J.B. Dakeyne, #37 S.F.T.S. ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~2. Hitting obstructions.~~

9. Collision (9)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action is being taken.

CONCLUSIONS OF A.I.B.

Instructor struck unattended parked tractor while taxiing on taxi strip. Evidence tends to excuse pilot for failure to make sure no obstacles in path. Condition of taxi strip prevented pilot from taxiing in proper manner. Considered driver of tractor partly to blame for parking where it might be hit.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Carelessness on part of pilot, failed to see tractor parked on edge of runway.~~

(For complete details see Summary of Accident Investigation No. 801)

RECORDED BY

DATE

CHECKED BY

DATE