

CASPIR Aircraft Accident Cards

Serial: FP790

Title: Avro Anson Mk. II serial:FP790 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-January-26. Anson II s/n FP790. This accident involved 2 people. Meyers PD, Monaghan JK

Keywords: RCAFAnson II,FP790,15 SFTS,15 Service Flying Training School,Aerodrome,1943-January-26,Meyers,MonaghanRCAF L20

Created: 1943-01-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP790>

DUTY ON WHICH ENGAGED:

Dual instruction on low flying sequence.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While demonstrating low flying pilot decided to demonstrate operational low flying. A/C struck the snow with the propellers and pitot head.

DATE:

D-1/4 ✓
1LCO/POL/WVS

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Discipline not instilled in pilot
Low flying in 30' area
Low flying area.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Since accident, pilot confined to hospital. No action taken pending return to duties.

~~17. Disobedience of Standing Orders.~~

22. Collision - Obstr. 22

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~An error in judgment.
Glare of sunlight on unbroken snow.~~

41
Disobedience of Orders.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____