

CASPIR Aircraft Accident Cards

Serial: FP830

Title: Avro Anson Mk. II serial:FP830 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-January-31. Anson II s/n FP830. This accident involved 1 person. Levenson L

Keywords: RAFAnson II,FP830,33 SFTS,33 Service Flying Training School,Aerodrome,1943-January-31,LevensonRCAF L20

Created: 1943-01-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP830>

DUTY ON WHICH ENGAGED:

Local training flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil struck telephone pole when undershooting on approach.

DATE:

LCO/PSJ

D-14

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Inexperience at night.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Endorsement of Log Book "Inexperience" and "Error of Judgment".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Error of judgment.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____