

TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE				CAUSES	
UNIT 124 Ferry Sqn.		COM. Rockcliffe, Ont.		AFHQ		PLACE 8 miles N. W. of Regina.				DATE 6-1-43		TIME 1000		H.O. FILE 1300-AN115	
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT		MISCELLANEOUS	
Hampden		AN115		B		X		X		X		X		HAND/O.	
NAME		RANK		No.		DUTY		INJURIES				SERIOUS		CAUSES	
Wheeler, C.T.		P/O		C14081		P		Nil				FATAL		INSTS.	
Cole, J.G.		W02		R82075				Nil				INJURY		WEATHER	
												CARD SERIAL No.		DRINKS.	
												X		ALG SURF.	
														OTHER	
														UND/TD	
														PRIMARY	
														TAXIING	
														LANDING	
														TAKE-OFF	
														FLIGHT	
														STATRY	
														FATAL	
														INJ.	
														3RD.	
														4	
														5	
														6	
														7	
														8	
														9	
														10	
														11	
														12	
														13	
														14	
														15	
														16	
														17	
														18	
														19	
														20	
														21	
														22	
														23	
														24	
														25	
														26	
														27	
														28	
														29	
														30	
														31	
														32	
														33	
														34	
														35	
														36	
														37	
														38	
														39	
														40	
														41	
														42	
														43	
														44	
														45	
														46	
														47	
														48	
														49	
														50	
														51	
														52	
														53	
														54	
														55	
														56	
														57	
														58	
														59	
														60	
														61	
														62	
														63	
														64	
														65	
														66	
														67	
														68	
														69	
														70	
														71	
														72	
														73	
														74	
														75	
														76	
														77	
														78	
														79	
														80	
														81	
														82	
														83	
														84	
														85	
														86	
														87	
														88	
														89	
														90	
														91	
														92	
														93	
														94	
														95	
														96	
														97	
														98	
														99	
														100	
CATEGORY		TYPE OF ENGINE		TYPE OF A/C		NATURE OF ACCIDENT									
Hampden		AN115		Serious											
Bristol		Nil		Nil											
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE					
A 286		6-1													

DUTY ON WHICH ENGAGED:

Ferry flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Stbd. engine failed. Pilot continued on port engine, but just before arriving at Regina port engine kept gradually failing and when on his cross wind leg prior to landing, it failed. Pilot tripped wheels and carried out a belly landing.

ADPD.14
~~SB/ES/AM/PA/PE/I/VO/K/B~~
FB/ADP/2006/ES/AM/PE/I/VO/K/B

RECOMMENDATIONS:

WIE

PRIMARY CAUSE:

8/13

54. ~~Engine failure in the air.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

(18)

18. Misc. Technical

SECONDARY CAUSE OR CONTRIBUTING FACTOR:

~~Ice in carburettor.~~

~~Engine trouble~~ Accident

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____