

DUTY ON WHICH ENGAGED:

Taxiing aircraft to parking line.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MPLT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft 7886 parked on line.
Aircraft 7673 taxied into 7886.

DATE:

TCA/PETV

COMPOSITION:

MH/XX

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Collision

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Gross Negligence of the pilot of
taxiing A/C. Absence of airmen
on the taxiing A/C wing tips when
approaching the line.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____