

DUTY ON WHICH ENGAGED:

Taxiing A/C.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil pilot taxiing towards parked A/C, applied brakes and skidded into parked Harvard AJ933.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

3. Hitting other A/C.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Action under T.C.I. 3/16. Log book endorsed. Ordered stoppage of pay to the extent of \$5. being half of the cost of damage to A/C concerned.

NOTE: Stoppage of pay contrary to existing regulations. A.O.C. asked to consider remittance of amount Letter 794-A-367 (D of P) (P.1) 8th March, 1943.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Carelessness on part of pilot.
Fast taxiing.

RECORDED BY

DATE

CHECKED BY

DATE