

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT 14 S.F.T.S. Aylmer, Ont.			COM. 1	PLACE Con. 5, Lot 22 Westminster Twp. Ont.				DATE 5-2-43		TIME 1300			
A/C TYPE Harvard II			No. 3094	CRASH CAT. A		SE X	ME	DAY X	NIGHT				
NAME Taylor, G.J.			RANK Aus.	No. LAC409959	DUTY PP	INJURIES Fatal			SERIOUS				
									FATAL 1	INJURY			
									CARD SERIAL No. X				
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS						
Harvard		3094	Total				INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.
WaspS3H1		1270/7381	Total						DUAL	SOLO	DUAL	SOLO	
SIGNAL No & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE			
A66		6-2											
NATURE OF ACCIDENT													

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

CAUSES

FLIGHT OF

- 60 TECH.
- 59 DISOB.
- 58 INEXP/NGE
- 57 MISCEL.
- 56 INSTRUCT.
- 55 FLT. CONTR.
- 54 OTHERS
- 53 PRIMARY
- 52 FL. CONTRS.
- 51 MOV. SURFS.
- 50 STAB. SURFS.
- 49 W. STRUTS
- 48 LAND GEAR
- 47 FLOATS
- 46 FUSE. OR HULL
- 45 TAIL SKID OR W.
- 44 ENGINE MOUNT.
- 43 MISCEL.
- 42 UND TD
- 41 PRIMARY
- 40 FUEL SYS.
- 39 COOL SYS.
- 38 IGNIT. SYS.
- 37 LUB'N. SYS.
- 36 ENG. STR.
- 35 AIRSCREW A.
- 34 ENG. CONTRS.
- 33 MISCEL.
- 32 UND TD
- 31 PRIMARY

- 19
 - 18
 - 17
 - 16
 - 15
 - 14
 - 13
 - 12
 - 11
 - 10
 - 9
 - 8
 - 7
 - 6
 - 5
 - 4
 - 3
 - 2
 - 1
- HAND Q.
 - INSTS.
 - WEATHER
 - DRKNS.
 - ALG SURF.
 - OTHER
 - UND TD
 - PRIMARY
 - TAXING
 - LANDING
 - TAKE-OFF
 - FLIGHT
 - STABTY
 - FATAL
 - INJ.
 - 3RD.
 - RAF
 - W.N.

- 1
 - 2
 - 3
 - 4
 - 5
 - 6
 - 7
 - 8
 - 9
 - 10
 - 11
 - 12
 - 13
 - 14
 - 15
 - 16
 - 17
 - 18
 - 19
- 1
 - 2
 - 3
 - 4
 - 5
 - 6
 - 7
 - 8
 - 9
 - 10
 - 11
 - 12
 - 13
 - 14
 - 15
 - 16
 - 17
 - 18
 - 19

DUTY ON WHICH ENGAGED:
Turns, TO into wind, E. assisted App. &
Lands., spins, steep turns, forced
landings and aerobatics.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT: ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pilot, while diving over school, de-
layed too long before pulling out of
dive, necessitating violent action,
causing aircraft to mush into ground.

DATE: 6-2-43
COMPOSITION:
F/L L.B. Elwin, No. 16 S.F.T.S., Hagersville, Ont.

RECOMMENDATIONS:
Residents should be encouraged to report any aircraft
observed low flying.

PRIMARY CAUSE:
~~16. Unauthorized low flying and
aerobatics:~~

Recommendations of Unit Commander - Removal from
aircrew pilot list and stripping of pilots badge
from pilots convicted of flagrant disregard for
low flying orders

20 New into Ground

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
C.O. has been requested to ensure that F.I. exercise
closer supervision of signing of L.14 by Pupil Pilots.
Conclusions of A.I.B.

Another case of deliberate unauthorized low flying
by a pupil pilot.
See "Nature of Accident and Stage of Flight"

SECONDARY CAUSE OR CONTRIBUTING FACTORS:
~~22. Stalling.~~

42 42 Unauthorized low flying

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____