

CASPIR ARCHIVAL METADATA

Serial:	1183
Title:	de Havilland Moth, Tiger I serial:1183 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 2 aircraft on 1943-February-10. They are: Tiger Moth s/n 5067, Tiger Moth s/n 1183. This accident involved 2 people. Johnson AC, Stamatis GT
Keywords:	RCAFTiger Moth ,1183,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-February-10,Johnson,StamatisRCAF L20
Created:	1943-02-10
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#1183

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Spinning, climbing turns, steep turns and forced landings
NATURE OF ACCIDENT AND STAGE OF FLIGHT:

OR COMMANDING OFFICER'S REPORT:

DATE:

COMPOSITION:

Tiger Moth 5067 taxied into Tiger Moth 1183 on taxi strip. Turned to avoid one A/C and on straightening out noticed another A/C directly in front. Applied brakes but to no avail, propellor cut through wing of other A/C.

RECOMMENDATIONS:

PRIMARY CAUSE:

3
9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed. Placed on charge.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Careless taxiing.~~

RECORDED BY

DATE

CHECKED BY

DATE