



DUTY ON WHICH ENGAGED:

Forced landings and steep turns.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine failed to function when throttle opened at completion of practiced forced landing, A/C hit snow and nosed over,

DATE:

COMPOSITION:

*DOT* *D-14*  
*1LFM/PCDL/ES/PM/PC/14*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~54. Engine failure in the air.~~

*17. Forced Landing*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*Nil.*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Student neglected to clear engine sufficiently.~~

*Ob Engine Trouble - Accident*

RECORDED BY

DATE

CHECKED BY

DATE