

TYPE OF A/C		CAUSES OF ACCIDENTS										MISCELLANEOUS											
TYPE OF ENGINE		STAGE OF FLIGHT										CAUSES											
CATEGORY		NATURE OF ACCIDENT										MISCELLANEOUS											
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE									
UNIT 10 E.F.T.S.		COM.		PLACE										DATE 20-2-43		TIME 1545							
Pendleton, Ont.		3		M.A.										H.Q. FILE 1100-89-63									
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT											
Tiger Moth		8963		D.1		X				X													
Tiger Moth		5881		C.1																			
NAME		RANK		No.		DUTY		INJURIES		SERIOUS													
Huntington, G.A.		Lac.		R164599		PP		NIL.		FATAL		INJURY											
Note: A/C 5881 parked unoccupied.										CARD SERIAL No.													
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS											
Tiger Moth 8963		Slight										INST. NIGHT											
G. Major 12808/89026		NIL										ON TYPE											
Tiger Moth 5881		Slight										TOTAL											
G. Major 1431/89273		NIL										LAST 6 MOS.											
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE													

DUTY ON WHICH ENGAGED:

Taxiing out to practice circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MVLT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxiing and looking out in order not to hit chocks in path ahead uper stbd mainplane collided with propellor of parked A/C.

DATE:

D-14

COMPOSITION:

TCA/PCT
MA/XA

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other A/C.~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Carelessness on part of pilot.

RECORDED BY

DATE

CHECKED BY

DATE