

## CASPIR Aircraft Accident Cards

---

**Serial:** AS921

**Title:** Airspeed Oxford Mk. II serial:AS921 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-February-27. Oxford II s/n AS921. This accident involved 1 person. Southall JS

**Keywords:** RAFOxford II,AS921,35 SFTS,35 Service Flying Training School,Kyle Saskatchewan,1943-February-27,SouthallRCAF L20

**Created:** 1943-02-27

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS921>



DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Lost on navigation flight and force landed with u/c retracted.

DATE:

COMPOSITION:

D-14  
FB/PC/PT/PS/PM/I Corp

RECOMMENDATIONS:

Further instruction.

PRIMARY CAUSE:

~~52. Lost and no gas.~~

17

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

17. Forced Landing

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Errors in map reading. Failure to exercise mental D.R.~~

25. Petrol Shortage 25

RECORDED BY

DATE

CHECKED BY

DATE