

## CASPIR Aircraft Accident Cards

---

**Serial:** FE320

**Title:** North American Harvard Mk. IIB serial:FE320 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-March-01. Harvard II s/n FE320. This accident involved 1 person. Hawkins GC

**Keywords:** RAFHarvard II,FE320,41 SFTS,41 Service Flying Training School,Aerodrome,1943-March-01,HawkinsRCAF L20

**Created:** 1943-03-01

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE320>



DUTY ON WHICH ENGAGED:

Night flying circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C landed with U/C retracted.

DATE:

D-14 ✓

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

34. Wheels up landing.

*4. Other*

7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed. Action under T.C.I. 3/19, and 14 days C .C.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

24. Carelessness.

*32. No call in 32  
air*

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_