

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Sequences 10-15-17-22.	OR COMMANDING OFFICER'S REPORT:
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C swerved to left after landing, began to ground loop, struck snow bank and nosed up.	DATE: COMPOSITION:
)	RECOMMENDATIONS:
PRIMARY CAUSE: 61. Swinging on landing	
2. Lucing	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
)))	Log book endorsed "Carelessness". Pilot was admonished by C.I. and awarded extra fatigue duties.
secondary cause or contributing factors: 36. Nosing up. 38. Ground Loop 32. Pilot Error	RECORDED BY DATE
	CHECKED BY DATE)