

Duty on which engaged: Sequence 11.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14
Pilot swung to left on landing run and failed to correct swing soon enough. A/C ground looped.	DATE: COMPOSITION:
	RECOMMENDATIONS:
PRIMARY CAUSE: 38. Ground Loop. 2. Junuary SECONDARY CAUSE OR CONTRIBUTING FACTORS: 32. Pilot error.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Log book endorsed "Error in Judgment". Personnel admonished by C.I.
	RECORDED BY DATE