

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ923

**Title:** North American Harvard Mk. II serial:AJ923 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-March-24. Harvard II s/n AJ923. This accident involved 1 person. Pexton RD

**Keywords:** RAFHarvard II,AJ923,34 SFTS,34 Service Flying Training School,Rose Lynn,1943-March-24,PextonRCAF L20

**Created:** 1943-03-24

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ923>

19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																				
CAUSES OF ACCIDENTS																																																		
UNIT No.34 S.F.T.S. Medicine Hat, Alta.										COM. # 4		PLACE Rose Lynn										DATE 24-3-43		TIME 1145																										
																						H.Q. FILE		1300-AJ923																										
A/C TYPE		Harvard II						No. AJ923		CRASH CAT		B		SE x		ME		DAY x		NIGHT																														
NAME						RANK		No		DUTY		INJURIES						SERIOUS																																
Pexton, R.D.						S/L		72150		P		Nil						FATAL		INJURY																														
																				CARD SERIAL No.																														
																				V																														
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																						
Harvard II		AJ923		Serious								INST. NIGHT		ON TYPE				TOTAL				LAST 6 MOS.																												
Wasp S3H1		4217		Slight										DUAL SOLO		DUAL SOLO		DUAL SOLO		DUAL SOLO																														
SIGNAL No & DATE				UNIT No. & DATE				COM. No & DATE				REPORT				FILE				DATE																														
Q986 24-3-43																																																		
NATURE OF ACCIDENT																																																		

TYPE OF AC

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

FLIGHT

19  
18  
17  
16  
15  
14  
13  
12  
11  
10  
9  
8  
7  
6  
5  
4  
3  
2  
1  
 32  
31  
30  
29  
28  
27  
26  
25  
24  
23  
22  
21  
20  
19  
18  
17  
16  
15  
14  
13  
12  
11  
10  
9  
8  
7  
6  
5  
4  
3  
2  
1  
 HAND O.  
INSTS.  
WEATHER  
DRKNS.  
AL'S SURF.  
OTHER  
UND/TD  
PRIMARY  
TAXING  
LANDING  
TAKEOFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJURY  
3RD.  
RAF  
W/N

DUTY ON WHICH ENGAGED:

Proceeding to crashed aircraft.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14.

*L. R. G. / H. T. C. / R. S. J. / ✓*

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Squadron Commander circled field adjacent to crashed A/C three times and field appeared to be stubble and good surface. On touching down A/C rolled a few yards, and then the wheels dropped in snow and A/C overturned.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~44. Bad surface.~~

*11. Others*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~37. Overturning.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_