

TYPE OF ACCIDENT		PILOT	OTHERS	AIRFRAME FAILURE	ENGINE FAILURE	MISCELLANEOUS	CAUSES	FLIGHT	STAGE OF
TYPE OF ENGINE		UNIT	COM.	PLACE	DATE	TIME	H.Q. FILE	HAND O.	INSTS.
CATEGORY		A/C TYPE	No.	CRASH CAT.	SE	ME	DAY	DRKNS.	WEATHER
		NAME	RANK	No.	DUTY	INJURIES	SERIOUS	ALG SURF.	OTHER
		Harrison, V.D.	Sgt.	984980	P.	NIL.	FATAL	INJURY	LND TD
		Butcher, P.J.	Lac.	1394318	AB	NIL.			PRIMARY
		Hughes, S.R.	P/O	124633	P.	NIL.			TAXIING
		Tilly, E.G.	Lac.	931477	AB	NIL.	CARD SERIAL NO.		LANDING
		Herrington, O.E.	Lac.	1577981	AB	NIL.			TAKE-OFF
		TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL NO.	DATE	INST.	NIGHT
		Anson 8213 Slight							
		Jacobs 2691/2518 Nil.							
		Bolingbroke 9867 Slight							
		Mercury 2815/2797 Nil.							
		SIGNAL No & DATE	UNIT No. & DATE	COM. No. & DATE	REPORT	FILE	DATE	DUAL	SOLO
		A-144	11-3-43						
		HOURS FLOWN BY PILOTS	ON TYPE	TOTAL	LAST 6 MOS.	DUAL	SOLO	DUAL	SOLO
		NATURE OF ACCIDENT							

MISCELLANEOUS CAUSES

19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
 PRIMARY
HAND O.
INSTS.
WEATHER
DRKNS.
ALG SURF.
OTHER
LND TD
PRIMARY
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
359.
RAF
N N

DUTY ON WHICH ENGAGED:

High level bombing.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MULT

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot of Anson applied brakes but wheels would not hold on surface due to ice conditions, A/C taxied into rear of Bolingbroke.

DATE:

COMPOSITION:

TCH/PCT/VB(XG) D-14
TCO/AIN

RECOMMENDATIONS:

PRIMARY CAUSE:

1. ~~Bad surface of aerodrome.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot admonished. Flying log book endorsed "Gross Carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

3. Hitting other aircraft.

24. Carelessness.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____