

CASPIR Aircraft Accident Cards

Serial: FP788

Title: Avro Anson Mk. II serial:FP788 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-March-27. Anson II s/n FP788. This accident involved 2 people. Callahan WJ, Gunson HAM

Keywords: RCAFAnson II,FP788,15 SFTS,15 Service Flying Training School,R1 Woodhouse,1943-March-27,Callahan,GunsonRCAF L20

Created: 1943-03-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP788>

DUTY ON WHICH ENGAGED:
Instructor practice.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
While taxiing in a strong wind the A/C started to ground loop and the stbd brake failed. On application of full rudder and motor the A/C failed to respond striking the Control Tender.

DATE:
COMPOSITION:

100/0137/10000 ✓
D-14

RECOMMENDATIONS:
More suitable brakes to be installed.

PRIMARY CAUSE:

~~7. Brake failure.~~

9. Collision

9

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~38. Ground loop.~~

~~2. Hitting Obstructions.~~

~~35. Cross winds and gusts.~~

36. Brake Failure

36

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____