

1	TECH.	PILOT	OTHERS	AIRFRAME FAILURE				ENGINE FAILURE				1	UNCRASHED		
2	DISOB.	CAUSES OF ACCIDENTS												2	PRIMARY
3	NEG INCE	UNIT	COM.	PLACE				DATE	TIME			3	HAND Q		
4	INEXPNCE	16 S.F.T.S.		1				29-3-43	0930			4	INSTS.		
5	MISCEL.	Hagersville, Ont.		4 miles North of Brantford				H.Q. FILE 1100-84-09				5	WEATHER		
6	INSTRUCT.	A/C TYPE	No.		CRASH CAT.		SE	ME	DAY	NIGHT	6	DRKNS.			
7	FLT. CONTR.	Anson 11	8409		B						7	AL & SURF			
8	OTHERS	Anson 11	FP896 D		01			X	X		8	OTHER			
9	PRIMARY	NAME		RANK	NO.	DUTY		INJURIES		SERIOUS		9	INDTD		
10	FL CONTRS	Russell, H.B.		F/O	J12466	P. Nil.				FATAL	INJURY	10	PRIMARY		
11	MOV SURFS.	Mason, A.W.		Cpl.	R65982	PP Nil.						11	TAXING		
12	STAB SURFS.	MacLeod, H.M.		Lac.	R153094	Pass. Nil.						12	LANDING		
13	W STRUTS	Weston, A.C.		Lac.	R96190	Pass. Nil.						13	TAKE-OFF		
14	LAND GEAR	Sherry, D.C.		P/O	J20612	P. Nil.						14	FLIGHT		
15	FLOATS	Miller, L.C.		GB	Lac.	934427	PP Nil.						15	STATRY	
16	FUSE OR HULL	Donnan, B.C.		Lac.	R156193	Pass. Nil.						16	FATAL		
17	TAIL SKID OR W											17	INI.		
18	ENGINE MOUNT											18	3RD.		
19	MISCEL.											19	4th		
20	INDTD											20	5th		
21	PRIMARY											21	6th		
22	FUEL SYS.											22	7th		
23	COOL SYS.											23	8th		
24	IGNIT. SYS.											24	9th		
25	LUB'N SYS.											25	10th		
26	ENG. STR.											26	11th		
27	AIRSCREW A.											27	12th		
28	ENG. CONTRS											28	13th		
29	MISCEL.											29	14th		
30	UNCRASHED											30	15th		
31												31	16th		
32												32	17th		
33												33	18th		
34												34	19th		
35												35	20th		
36												36	21st		
37												37	22nd		
38												38	23rd		
39												39	24th		
40												40	25th		
41												41	26th		
42												42	27th		
43												43	28th		
44												44	29th		
45												45	30th		
46												46	31st		
47												47	32nd		
48												48	33rd		
49												49	34th		
50												50	35th		
51												51	36th		
52												52	37th		
53												53	38th		
54												54	39th		
55												55	40th		
56												56	41st		
57												57	42nd		
58												58	43rd		
59												59	44th		
60												60	45th		
61												61	46th		
62												62	47th		
63												63	48th		
64												64	49th		
65												65	50th		
66												66	51st		
67												67	52nd		
68												68	53rd		
69												69	54th		
70												70	55th		
71												71	56th		
72												72	57th		
73												73	58th		
74												74	59th		
75												75	60th		
76												76	61st		
77												77	62nd		
78												78	63rd		
79												79	64th		
80												80	65th		
81												81	66th		
82												82	67th		
83												83	68th		
84												84	69th		
85												85	70th		
86												86	71st		
87												87	72nd		
88												88	73rd		
89												89	74th		
90												90	75th		
91												91	76th		
92												92	77th		
93												93	78th		
94												94	79th		
95												95	80th		
96												96	81st		
97												97	82nd		
98												98	83rd		
99												99	84th		
100												100	85th		

CAUSES OF ACCIDENTS

UNIT 16 S.F.T.S. COM. PLACE 4 miles North of Brantford DATE 29-3-43 TIME 0930
 Hagersville, Ont. 1 H.Q. FILE 1100-84-09

A/C TYPE Anson 11 No. 8409 CRASH CAT. B SE ME DAY NIGHT
 Anson 11 FP896 D 01 X X

NAME	RANK	NO.	DUTY	INJURIES	SERIOUS
					FATAL INJURY
Russell, H.B.	F/O	J12466	P. Nil.		
Mason, A.W.	Cpl.	R65982	PP Nil.		
MacLeod, H.M.	Lac.	R153094	Pass. Nil.		
Weston, A.C.	Lac.	R96190	Pass. Nil.		
Sherry, D.C.	P/O	J20612	P. Nil.		
Miller, L.C.	GB	Lac. 934427	PP Nil.		
Donnan, B.C.	Lac.	R156193	Pass. Nil.		

TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS					
						INST.	NIGHT	ON TYPE		TOTAL	LAST 6 MOS.
						DUAL	SOLO	DUAL	SOLO		
Anson 8409	Seriously										
Jacobs L6MB	P13951/P25262	S26839/S10093	Nil.								
Anson FP896	Slightly										
Jacobs L6MB	P25975/P10679	S11603/S14632	Nil.								

SIGNAL No. & DATE A-37 29-3-43 UNIT No. & DATE COM. No. & DATE REPORT FILE DATE

NATURE OF ACCIDENT

100
99
98
97
96
95
94
93
92
91
90
89
88
87
86
85
84
83
82
81
80
79
78
77
76
75
74
73
72
71
70
69
68
67
66
65
64
63
62
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1

DUTY ON WHICH ENGAGED:
Formation flight.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

MVL 1

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Stbd wing tip of Anson FP896 slid over the outer top port surface on tail plane of Anson 8409 applying sufficient pressure to buckle several cross members in tail section of fuselage on Anson 8409.

DATE:

ICA/PCL ✓

COMPOSITION:

ICA/XA ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~26. Collision in the air.~~

21. Collision a/c.
21

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____