

19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61			
CATEGORY		TYPE OF ENGINE										TYPE OF A/C										MISCELLANEOUS		STAGE OF FLIGHT																										
A/C TYPE		NAME		RANK		No.		DUTY		INJURIES		SERIOUS		TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																
Ventura I		Gardner, R.		GB SGT		1233464		PP		Nil		FATAL		Ventura I AE678		Slight																																		
Type		Pallett, C.G.		SGT		R141179		WAG		Nil		INJURY		P&W Wasp P. - A199031		S. - A199034		Nil		Slight																														
UNIT		COM.		PLACE		DATE		TIME		HQ FILE		CARD SERIAL No.		SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		NATURE OF ACCIDENT																								
No.34 O.T.U., Pennfield Ridge		EAC		6 miles N.W. Pennfield Ridge Aerodrome		6-3-43		1140		1300-AE678		A 734 7-3-43																																						
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE										HAND Q.		PRIMARY																								
CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS		CAUSES OF ACCIDENTS														
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE										HAND Q.		PRIMARY																								
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE										HAND Q.		PRIMARY																								

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Single engine flying and landings.

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

While carrying out unauthorized low flying, the starboard wing collided with trees and A/C was damaged. The pilot landed safely at Base.

COMPOSITION:

11C0/PSU/POL ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~17. Disobedience of standing orders.~~

22. *Ballisuein Obstructions*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*21*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~16. Unauthorized low flying or aerobatics. Collision with trees.~~

42. *Unauthorized Low Flying*

RECORDED BY

DATE

CHECKED BY

DATE