

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	5840
<b>Title:</b>	de Havilland Moth, Tiger I serial:5840 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1943-March-27. Tiger Moth s/n 5840. This accident involved 2 people. Hinchey GW, Braithwaite JW
<b>Keywords:</b>	RCAFTiger Moth ,5840,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-March-27,Braithwaite,HincheyRCAF L20
<b>Created:</b>	1943-03-27
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5840">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5840</a>



DUTY ON WHICH ENGAGED:

Sequence 7,9. Night

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/c dragged stbd wing on take-off swerving off runway and running into snowdrift. A/c then turned over on its back.

DATE:

COMPOSITION:

02/PS/XGN ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~9. Swinging.~~

12. Swinging.

12

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed for "carelessness".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~11. Hitting obstructions.~~

~~37. Overturning.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_