

CASPIR Aircraft Accident Cards

Serial: 3346

Title: North American Yale serial:3346 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-March-09. Yale NA64 s/n 3346. This accident involved 2 people. Gagnon JA, Johnson GW

Keywords: RCAFYale NA64,3346,4 WSFS,4 Wireless School Flying Squadron,South Of Ayr Ontario,1943-March-09,Gagnon,JohnsonRCAF L20

Created: 1943-03-09

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001795#3346>

DUTY ON WHICH ENGAGED:

Instrument time under hood.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine did not respond to throttle, attempted to de-ice carburettor by full heat control, but was unable to do so. Force landed in hilly country, a/c struck deep snow, partially ground looped, stood on nose and fell back.

DATE:

COMPOSITION:

FC/AC/PC/SC/PA/MA/...

RECOMMENDATIONS:

PRIMARY CAUSE:

~~(47) Weather~~

17. Forced Landing

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~(54) Engine failure in the air.~~

26. Engine trouble accident

RECORDED BY

DATE

CHECKED BY

DATE