

CASPIR Aircraft Accident Cards

Serial: FE462

Title: North American Harvard Mk. IIB serial:FE462 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-April-01. They are: Harvard II s/n FE442, Harvard II s/n FE462. This accident involved 1 person. Walker SAD

Keywords: RAFHarvard II,FE462,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-01,WalkerRCAF L20

Created: 1943-04-01

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE462>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Taxiing.

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

✓

Pilot taxiing A/C up apron past stationary A/C, following application of brakes tip of port wing collided with stationary propellor of A/C ~~NE442.~~

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed and 7 days C.C.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____