

CASPIR Aircraft Accident Cards

Serial: 2701

Title: North American Harvard Mk.II serial:2701 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-April-03. They are: Harvard II s/n FE281, Harvard II s/n 2701. This accident involved 3 people. Hargreaves FE, Beardsall GJ, Wyatt FC

Keywords: RAFHarvard II,2701,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-03,Beardsall,Hargreaves,WyattRCAF L20

Created: 1943-04-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2701>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

FE281 - Circuits and landings.

OR COMMANDING OFFICER'S REPORT:

2701 - Precautionary landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Harvard 2701 while making final

COMPOSITION:

approach **suddenly** noticed A/C FE281

immediately above him. Propellor of 2701

struck U/C of FE281, causing A/C 2701 to

make heavy landing and nosed up. A/C RECOMMENDATIONS:

FE281 made further circuits and finally

made belly landing.

PRIMARY CAUSE:

~~26. Collision in the air.~~

21. Collision *etc.*

21

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE