

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ922

**Title:** North American Harvard Mk. II / 2 serial:AJ922 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-08. Harvard II s/n AJ922. This accident involved 1 person. Spellman PJ

**Keywords:** RAFHarvard II,AJ922,41 SFTS,41 Service Flying Training School,Halbrite R1,1943-April-08,SpellmanRCAF L20

**Created:** 1943-04-08

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ922>



DUTY ON WHICH ENGAGED:

Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot undershot, A/C touched down  
in mud causing swing and resultant  
ground loop.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~30. Undershooting runway.~~

*2. Undershot*

(3)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~38. Ground loop.~~

~~32. Pilot error.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_