

CASPIR Aircraft Accident Cards

Serial: 2759

Title: North American Harvard Mk.II serial:2759 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-13. Harvard II s/n 2759. This accident involved 1 person. Gardner E

Keywords: RAFHarvard II,2759,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-13,GardnerRCAF L20

Created: 1943-04-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2759>

DUTY ON WHICH ENGAGED:

Aerobatics.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil pilot making crosswind landing overcorrected and starboard oleo leg collapsed.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

61. Swinging on landing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

38. Ground loop.

35. Cross winds and gusts.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____