

CASPIR ARCHIVAL METADATA

Serial:	FP966
Title:	Avro Anson Mk. II serial:FP966 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1943-April-28. Anson II s/n FP966. This accident involved 3 people. O'Connell DS, Thompson S, Tunstall ET
Keywords:	RCAFAnson II,FP966,8 BGS,8 Bomb & Gunnery School,Aerodrome,1943-April-28,O'Connell,Thompson,TunstallRCAF L20
Created:	1943-04-28
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP966

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Routine bombing schedule flight.

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot was attempting to park A/C in parking space. In doing so he let A/C swing around, hitting fence post with stbd. wing tip.

COMPOSITION:

TCO/RET

RECOMMENDATIONS:

PRIMARY CAUSE:

~~2. Hitting obstructions.~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's Log Book endorsed and logged.

9

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____