



DUTY ON WHICH ENGAGED:

Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14. *M...*

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

One aircraft failed to recognize direction in which other A/C was travelling.

DATE:

COMPOSITION:

*TCA/11/11*  
*TCA/11/11*

RECOMMENDATIONS:

Floodlights directed on to parking area are now being used to prevent any re-occurrence of this type of accident.

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

*9. collisions*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_