

CASPIR Aircraft Accident Cards

Serial: AS738

Title: Airspeed Oxford Mk. II serial:AS738 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-04. Oxford II s/n AS738. This accident involved 2 people. Steainstreet A, Hesketh J

Keywords: RAFOxford II,AS738,35 SFTS,35 Service Flying Training School,Aerodrome,1943-April-04,Hesketh,SteainstreetRCAF L20

Created: 1943-04-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS738>

DUTY ON WHICH ENGAGED:

Day flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14
✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swung on landing, ran off end of runway and nosed up in soft snow.

DATE:

COMPOSITION:

LS / ANI / 1-5-51

RECOMMENDATIONS:

PRIMARY CAUSE:

~~36. Nosing up.~~

2. Swung

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor interviewed.

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~61. Swinging on landing.~~

~~25. Inexperience.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____