

DUTY ON WHICH ENGAGED:

8976 - test pupil pilot for C.T.
1222 - practice sequences 6,7,8,10,

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

M. H.

NATURE OF ACCIDENT AND STAGE OF FLIGHT: 12,15

DATE:

D-14

8976 on parking line and 1222 with
a solo pupil taxied into 8976 and
damaged the rudder. A/C 1222
was on skis at the time.

COMPOSITION:

TCA/PLT ←
TCA/A ←

RECOMMENDATIONS:

Solo students on skis should be impressed more
on importance of not approaching parked a/c.

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Leavings

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

25. Inexperience.

RECORDED BY

DATE

CHECKED BY

DATE