

DUTY ON WHICH ENGAGED:

Dual instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

1287 right inter-plane strut struck the trailing edge of left upper main plane of other A/C 1223.

DATE:

COMPOSITION:

D-1206/11
TCA/1206
TCA/1206

RECOMMENDATIONS:

PRIMARY CAUSE:

3. ~~Hitting other aircraft.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Logged and log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

24. ~~Carelessness.~~

RECORDED BY

DATE

CHECKED BY

DATE