

CASPIR Aircraft Accident Cards

Serial: AJ916

Title: North American Harvard Mk. II serial:AJ916 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-02. Harvard II s/n AJ916. This accident involved 2 people. Carruthers ER, Robinson JD

Keywords: RAFHarvard II,AJ916,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-02,Carruthers,RobinsonRCAF L20

Created: 1943-05-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ916>

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

PILOT		OTHERS		AIRFRAME FAILURE								ENGINE FAILURE											
CAUSES OF ACCIDENTS																							
UNIT No.41 S.F.T.S., Weyburn, Sask.				COM. # 2		PLACE M.A.				DATE 2-5-43				TIME 2130									
A/C TYPE Harvard II				No. AJ 916				CRASH CAT. C 1				SE X		ME		DAY		NIGHT X					
NAME				RANK		No.		DUTY		INJURIES				SERIOUS									
Carruthers, E.R.				SGT		1315339		FI		Nil				FATAL		INJURY							
Robinson, J.D.				LAC		1458814		PP		Nil													
														CARD SERIAL NO.									
														X									
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS											
Harvard II		AJ916		Slight								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.					
Wasp S3H1		5476		Nil								45 76		87 457		151 526							
														677									
SIGNAL No. & DATE				UNIT No & DATE				COM. No & DATE				REPORT				FILE				DATE			

NATURE OF ACCIDENT

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1
- 19
- 18
- 17
- 16
- 15
- 14
- 13
- 12
- 11
- 10
- 9
- 8
- 7
- 6
- 5
- 4
- 3
- 2
- 1

PRIMARY
 HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STAIRY
 FATAL
 INJ.
 3RD.
 RNF
 W N

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY. INVESTIGATING OFFICER

Night flying circuits and landings. OR COMMANDING OFFICER'S REPORT:

D-14 # 31.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Flying Instructor made heavy landing COMPOSITION:

Inspection following landing revealed
no damage, but following morning it was
discovered that stbd. oleo leg was bent.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~40. Heavy landing - flying into
ground.~~

4. Heavy

4

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Placed on charge for disobedience of Flight
Order No.57, and Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~17. Disobedience of standing orders.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____