Ç			RERAME	PAILL		CEL JAD OR			FAIL		120 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
OF A	UNIT NO.41 S.E.T.S. COM.		SES O ACE	F AC	CIDE	NTS	DATES-		TIME 1		Hr.HO.
ΥPE	Weyburn, Sask. # 2		M • A	. •			H.Q. FILE	7 10	JI		MEATHE MEATHE
F	TYPE Harvard II	No	. BW 20	3 c	RASH AT. C	2	se x	ME	DAY	NIGHT 0	
_	NAME	RANK	No.	DUTY		HULKI	: ES		SERI] 0 0 20°
	Webb, T.G.	LAC	1580675	PP	Nil		MARKET NO.		FATAL	INJURY C	DRATE OF SUR
Ш										(0) Lt	[/ x**/
Z :0 Z									CA		1/.6°/
ш									SERIA	L No,	14
PE OF						·				$ \vee \sqcap$	1/3/2
ΤY	TYPE A/F No EXTENT	REPO	ORT SERIAL	DATE		НОГ	JRS FLOW	N BY PIL	OTS		1/0/
	& ENGINE OF DAMAG		RM No.		INST.	NIGHT-	ON TYPE		OTAL	LAST TI	TAKE!
_	Harvard II BW203 Slight				8	5	6 1			6 MOS.	10/11
۲	Wasp S3Hl 13088 Nil				0	- U	6 1	50	45	G H	/ (0 /
00	· -										
CATE	SIGNAL NO. & DATE UNIT No. &	DATE	COM,	No. & DA	TE	REPOR	Т	FILE	D	ATE	K
٩				O F	ACCIE						± 2

DUTY ON WHICH ENGAGED: Exercises 6, 7, 8.	COURT OF INQUIRY. INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:))
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pupil pilot making landing, made three point landing but A/C swung to right. Corrective action was	D-41 # 45. DATE: COMPOSITION:)
applied, but A/C ran off runway.	RECOMMENDATIONS:)
PRIMARY CAUSE: 61. Swinging on landing: Swung)
2)	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other)
	NIL)
secondary cause or contributing factors: 35. Cross winds and gusts.	RECORDED BY DATE	j
	CHECKED BY DATE)