

CASPIR Aircraft Accident Cards

Serial: AH194

Title: North American Harvard Mk. II serial:AH194 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-14. Harvard II s/n AH194. This accident involved 2 people. Keyes AH, Blackburn EW

Keywords: RAFHarvard II,AH194,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-14,Blackburn,KeyesRCAF L20

Created: 1943-05-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AH194>

DUTY ON WHICH ENGAGED:

circuits & landings

COURT OF INQUIRY, INVESTIGATING OFFICER

D.14 #72

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Instructor taxiing a/c applied
brakes harshly at low speed
causing tail to rise & damaging
propellor.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~24. Carelessness~~

11. OTHERS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Summary of evidence ordered under T.C.I. 3/16

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~34. Harsh use of brakes~~

~~36. Nosing up~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____