

CASPIR Aircraft Accident Cards

Serial: 3202

Title: North American Harvard Mk.II serial:3202 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-19. Harvard II s/n 3202. This accident involved 2 people. Workman MC, Driver T

Keywords: RAFHarvard II,3202,41 SFTS,41 Service Flying Training School,Talmadge,1943-May-19,Driver,WorkmanRCAF L20

Created: 1943-05-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3202>

TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE						ENGINE FAILURE									
TYPE OF ENGINE		UNIT #41 S.F.T.S.		COM. 2		PLACE Talmadge						DATE 19.5.43		TIME 1000							
CATEGORY		A/C TYPE Harvard II		No. 3202		CRASH CAT. C.1		SE X		ME		DAY X		NIGHT							
TYPE OF A/C		NAME		RANK		No.		DUTY		INJURIES				SERIOUS							
TYPE OF ENGINE		Workman, M.C.		FO		129389		FI		Nil				FATAL INJURY							
CATEGORY		Driver, T.		LAC		1399146		PP		Nil				CARD SERIAL NO. X							
TYPE OF A/C		TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS							
TYPE OF ENGINE		Harvard		3202		NIL.								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.	
CATEGORY		Wasp 10095/213455		Aircrew blades bent.										53 71		85 443		147 510			
TYPE OF A/C		SIGNAL No & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE									
TYPE OF ENGINE		A.71		20.5.43																	
CATEGORY		NATURE OF ACCIDENT																			

CAUSES
 MISCELLANEOUS
 STAGE OF FLIGHT

HAND O.
 INSTS.
 WEATHER
 DRKMS.
 ALG SURF.
 OTHER
 UND'TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.
 INJURY

33
 32
 31
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

DUTY ON WHICH ENGAGED:
Low flying Cross country.

COURT OF INQUIRY. INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

F-14 #99

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
While flying over Talmadge on low flying cross country pilot lost height to ground level. A/C prop. struck ground. Obligated to make forced landing with wheels down.

DATE:
COMPOSITION:



RECOMMENDATIONS:

PRIMARY CAUSE:
~~16. Unauthorized low flying or aerobatics~~

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

20. ²⁰ FLEW INTO GROUND.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

42. UNAUTH. ⁴² LOW FLYING.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____