

CASPIR Aircraft Accident Cards

Serial: FE869

Title: North American Harvard Mk. IIB serial:FE869 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-23. Harvard IIB s/n FE869. This accident involved 2 people. Saltmarsh LJ, Bullough RO

Keywords: RAFHarvard IIB,FE869,34 SFTS,34 Service Flying Training School,Aerodrome,1943-May-23,Bullough,SaltmarshRCAF L20

Created: 1943-05-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE869>

DUTY ON WHICH ENGAGED:
Essential dual exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14 #119

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
A/C collided with a tractor while
taxiing.

DATE:
COMPOSITION:



RECOMMENDATIONS:

PRIMARY CAUSE:
~~2. Hitting obstructions.~~

9. COLLISIONS

9

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____