

CASPIR Aircraft Accident Cards

Serial: FE456

Title: North American Harvard Mk. IIB serial:FE456 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-27. Harvard IIB s/n FE456. This accident involved 1 person. Isbister J

Keywords: RAFHarvard IIB,FE456,34 SFTS,34 Service Flying Training School,Aerodrome,1943-May-27,IsbisterRCAF L20

Created: 1943-05-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE456>

DUTY ON WHICH ENGAGED:

Solo exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #158

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil carrying out local solo exercises at time of accident. After landing A/C ground looped.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

38. Ground loop.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

35. Cross winds and gusts.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____