	16. 46. 46. 46. 46. 46. 46. 46. 46. 46. 4	~~~	E 12 12 15 15 15 15 15 15 15 15 15 15 15 15 15				2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	106 146 "145 146"	
√	PILOT	OTHERS		USES O			ENGIN	E FAILURE	<u> </u>
TYPE OF	O UNIT #37 S.F.T.S. COM.			PLACE Dalroy, Alta.			DATE 20.5.43 TIME 1840		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
<u>`</u>	A/C TYPE A1	nson II		No. 74 0		CRASH CAT. B	SE ME	DAY NIGHT	S WEBY
$^{\wedge}\mathcal{H}$		N ME	RA	NK NO.	DUTY	חראו	RIES	SERIOUS]> [0 ⁶ / ₂ / ₂ /
GINE	Jeffery Casley	у, В.Р. , W.Н.	1	90 15171 90 15125		Nil Nil		FATAL INJURY	TO Z
E OF EN		A CONTRACTOR AND ADDRESS OF THE CONTRACTOR A					7,000	CARD SERIAL NO.	S D S D S ATT
A TYP	TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT SERIAL FORM No.	DATE	НС	OURS FLOWN BY F	TOTAL	111/37
GORY &	Anson Jacob F	7404 t15215/2: 062/1587	Serious 526 Serio Nil.			29 25 29 32		7AL SOLO 6 MOS.	T A O E QUIST
CATE	SIGNAL NO	.& DATE	UNIT NO. & DA	TE COM	 . No. & D. 	ATE REPO	RT FILE	DATE	THE STREET AND THE ST

DUTY ON WHICH ENGAGED: General flying practices.	COURT OF INQUIRY, INVESTIGATING OFFIC OR COMMANDING OFFICER'S REPORT:	<u>er</u> D <i>-</i> 14	#40	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION: // //5		-	
ractice, pilot failed to take action por enough. A/C struck straw pile				
ed stbd engine failed.	RECOMMENDATIONS:			
PRIMARY CAUSE: 32. Pilot error.				
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTH	ER		
secondary cause or contributing factors:		DECORDED BY		DATE
		RECORDED BY		DATE
		CHECKED BY		DATE