

CASPIR ARCHIVAL METADATA

Serial:	9908
Title:	Bristol Bolingbroke Mk. IVT serial:9908 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1943-May-18. Bolingbroke IVT s/n 9908. This accident involved 4 people. Crichton AN, Frederick AE, Stainback RE, Taylor RKG
Keywords:	RCAFBolingbroke IVT,9908,8 BGS,8 Bomb & Gunnery School,Aerodrome,1943-May-18,Crichton,Frederick,Stainback,TaylorRCAF L20
Created:	1943-05-18
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000258#9908

DUTY ON WHICH ENGAGED:

Routine gunnery schedule flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #7

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C landed, after rolling a short distance port tire blew out causing A/C to ground loop. When half way around in the groundloop, stbd U/C broke and port U/C folded.

DATE:

COMPOSITION:

LUC/UTB/USM

RECOMMENDATIONS:

PRIMARY CAUSE:

~~43. Tire trouble.~~

Swung.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~38. Ground loop~~

TYRE BURST

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____