

DUTY ON WHICH ENGAGED:

Instructors instrument flight.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14 #25

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Whilst taxiing A/C 10563 after
landing pilot taxied into 2
stationary A/C.

DATE:

COMPOSITION:

TCA / PCT
MA / MA
MA / MA

RECOMMENDATIONS:

PRIMARY CAUSE:

32. Pilot error.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

P/O Baldwin placed under arrest.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

3. Hitting other aircraft.

14. Misuse of controls.

RECORDED BY

DATE

CHECKED BY

DATE