

CASPIR ARCHIVAL METADATA

| | |
|------------------|---|
| Serial: | 4169 |
| Title: | de Havilland Moth, Tiger I serial:4169 Accident Card |
| Author: | Royal Canadian Air Force (RCAF) |
| Subject: | This accident involved 1 aircraft on 1943-May-04. Tiger Moth s/n 4169. This accident involved 1 person. Dyker AL |
| Keywords: | RCAFTiger Moth ,4169,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-May-04,DykerRCAF L20 |
| Created: | 1943-05-04 |
| Link: | https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#4169 |

DUTY ON WHICH ENGAGED:

Seq. 7,9., Second solo

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14#7 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

On cross wind leg & attempting to turn into wind allowed a/c to stall & spin; recovered at insufficient height to avoid C.P.R. telephone lines, struck wires & crashed on railway track.

DATE:

COMPOSITION:

LOC/ACC/PSF/A/N

RECOMMENDATIONS:

PRIMARY CAUSE:

~~25. Inexperience~~

19. OUT. OF CONTROL.

19

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~22. Stalling~~

~~23. Spinning~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____