

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	5093
<b>Title:</b>	de Havilland Moth, Tiger I serial:5093 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1943-May-22. Tiger Moth s/n 5093. This accident involved 2 people. Ostrander JB, Tarzwell HC
<b>Keywords:</b>	RCAFTiger Moth ,5093,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-May-22,Ostrander,TarzwellRCAF L20
<b>Created:</b>	1943-05-22
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5093">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5093</a>



DUTY ON WHICH ENGAGED:

Seq. 6,7,9,16.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #75

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Practicing a takeoff, A/C ground looped, stbd wing catching ground overturning A/C.

DATE:

COMPOSITION:

OS/A70/PSE

RECOMMENDATIONS:

Instructor transferred to flight with senior students while he gains experience.

PRIMARY CAUSE:

~~1. Swinging.~~

2. SWUNG.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Instructor paraded.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~12. Loss of control.~~

~~25. Inexperience.~~

37. Overturning

38. Ground loop

RECORDED BY

DATE

CHECKED BY

DATE