

CASPIR Aircraft Accident Cards

Serial: 3259

Title: North American Harvard Mk.IIB serial:3259 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-01. Harvard IIB s/n 3259. This accident involved 1 person. Trobe KM

Keywords: RAFHarvard IIB,3259,34 SFTS,34 Service Flying Training School,Aerodrome,1943-June-01,TrobeRCAF L20

Created: 1943-06-01

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3259>

) PURPOSE OF FLIGHT:

) Solo formation exercises.

) TECHNICAL OFFICER'S REPORT:

) Nil.

) NATURE OF ACCIDENT:

) Landed in gusty wind which caused
) a wing to drop and scrape on
) the runway.

) COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

) FINDINGS:

) SUMMARY No.

) CLASSIFICATION:

) 35. Cross winds and gusts.

) SECONDARY OR CONTRIBUTORY FACTORS:

) ACTION TAKEN:

) Nil.