

CASPIR Aircraft Accident Cards

Serial: 2569

Title: North American Harvard Mk.II serial:2569 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-05. Harvard II s/n 2569. This accident involved 2 people. Murcek VO, Skrimar J

Keywords: RAFHarvard II,2569,34 SFTS,34 Service Flying Training School,Aerodrome,1943-June-05,Murcek,SkrimarRCAF L20

Created: 1943-06-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2569>

PURPOSE OF FLIGHT:

Local formation flying

NATURE OF ACCIDENT:

A/C landed and ground looped.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

38. Ground Loop

SECONDARY OR CONTRIBUTORY FACTORS:

25. Inexperience

ACTION TAKEN:

Nil