

TYPE OF A/C	UNIT #1 S.F.T.S. Camp Borden	COM. 1	PLACE Utopia, Ont.	DATE 6.6.43		TIME 0930		COMMAND
				H.Q. FILE 1100-29-67		DAY X	NIGHT	
TYPE OF UNIT	A/C TYPE Harvard II	No. 2967	CRASH CAT. C.7	S.E. X	M.E.			DAY X
						PERSONNEL Simmons, D.B.	RANK LAC	
CATEGORY	ENGINE asp	ENGINE NUMBER (S) 4725/5595	Slight	INST. 22	NIGHT 4			HOURS FLOWN BY PILOTS
						ON TYPE	TOTAL	
SOLO 21	DUAL 33	SOLO 53	DUAL 75	FORCED LANDINGS	TAYING			LANDING
						STATRY	FATAL	
RAF	M	N	S					

ACCIDENT CLASSIFICATION

ACCIDENT CLASSIFICATION

11/11/43

PURPOSE OF FLIGHT:

Cross country No. 5

NATURE OF ACCIDENT:

Severe vibration developed which the cutting of switches did not stop. Made wheels up landing into wind.

TECHNICAL OFFICER'S REPORT:

One propellor blade broken off about 3" from tip. Indications are that blade failed in the air.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~33. Technical defect~~
18. Misc. Technical 18

SECONDARY OR CONTRIBUTORY FACTORS:

35. W/c Defect.

35-

ACTION TAKEN:

Nil