

## CASPIR Aircraft Accident Cards

---

**Serial:** 2571

**Title:** North American Harvard Mk.II serial:2571 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-June-08. Harvard II s/n 2571. This accident involved 2 people. Chrisp CR, Lee AR

**Keywords:** RAFHarvard II,2571,34 SFTS,34 Service Flying Training School,Aerodrome,1943-June-08,Chrisp,LeeRCAF L20

**Created:** 1943-06-08

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2571>



PURPOSE OF FLIGHT:

Local dual exercises.

TECHNICAL OFFICER'S REPORT:

Nil.

NATURE OF ACCIDENT:

A/C swung to stbd on landing, stbd oleo leg was distorted during the swing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY NO.

CLASSIFICATION:

~~35. Cross winds and gusts.~~

2. *Swing.*

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~14. Misuse of controls.~~

34. *w/c Strain*

(34)

ACTION TAKEN:

Nil.