

PURPOSE OF FLIGHT:

Taxiing.

TECHNICAL OFFICER'S REPORT:

Nil.

NATURE OF ACCIDENT:

Pilot of A/C 3233, failing to keep a sharp lookout, taxied into A/C 2635 which was parked at side of runway waiting to take off.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~ 9

COLLISIONS.

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Pilot of A/C 3233 log book endorsed "carelessness".
Grounded for 30 days.