

CASPIR Aircraft Accident Cards

Serial: AJ940

Title: North American Harvard Mk. II / 2A serial:AJ940 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-10. Harvard II s/n AJ940. This accident involved 1 person. English RS

Keywords: RAFHarvard II,AJ940,41 SFTS,41 Service Flying Training School,Aerodrome,1943-June-10,EnglishRCAF L20

Created: 1943-06-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ940>

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn	COM. 2	PLACE M.A.	DATE 10.6.43	TIME 0035
A/C TYPE Harvard II	No. AJ.940	CRASH CAT. C.3	H.Q. FILE 1300-AJ.940	
			S.E. X	M.E. DAY
				NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
English, R.S.	LAC	1805315	PP	Nil	NO. A.80	DATE 10.6
					D 14 (REVISED)	
					NO. 4	CHECKED <input checked="" type="checkbox"/>
					#40	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp 33H1 Y128/1282	Slightly	13	6	39	45	73	76

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT RV
FATAL
INJ.
INJURY 3RD
5
RAF
M N

152
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
CATEGORY
TYPE OF UNIT
TYPE OF A/C

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61

PURPOSE OF FLIGHT:

Solo night flying circuits and landings.

NATURE OF ACCIDENT:

Pupil flying solo overcorrected slight swing on night landing and damaged oleo leg.

TECHNICAL OFFICER'S REPORT:

NIL.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~1. Swinging on landing.~~ 2

2. Swing.

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

34. WIC Strain. 34

ACTION TAKEN:

NIL.