

CASPIR Aircraft Accident Cards

Serial: 2654

Title: North American Harvard Mk.II / IIA serial:2654 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-15. Harvard II s/n 2654. This accident involved 1 person. Byrne DJ

Keywords: RAFHarvard II,2654,41 SFTS,41 Service Flying Training School,Aerodrome,1943-June-15,ByrneRCAF L20

Created: 1943-06-15

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2654>

102 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 41 S.F.T.S. Weyburn	COM. 2	PLACE M.A.	DATE 15.6.43	TIME 1500
A/C TYPE Harvard II		No. 2654	CRASH CAT. C.1	H.O. FILE 1100-26-54
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

4
2
1
7
4
2
1

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Byrne, D.J.	LAC	1453931	PP	Nil	No. A.87	DATE 16.6
					D 14 (REVISED)	
					No. 10	CHECKED
					#71	

MONTH

4
2
1

FORCED LANDING
TAXIING
LANDING
TAKEOFF

STAGE OF FLIGHT

ENGINE Wasp 93H1 135/1288/4072 Nil.	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		10	5	4	8	47	47

FLIGHT
STATRY
FATAL
INJ
INJURY 3RD
S

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

TYPE OF A/C

TYPE OF UNIT

CATEGORY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

PURPOSE OF FLIGHT:

Exercises 6,7,8.

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

Pupil ground looped on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Ground loop.~~

2. *Swung*

L

SECONDARY OR CONTRIBUTORY FACTORS:

~~35. Cross winds and gusts.~~

ACTION TAKEN:

NIL.