

CASPIR Aircraft Accident Cards

Serial: AJ944

Title: North American Harvard Mk. II / 2A serial:AJ944 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-16. Harvard II s/n AJ944. This accident involved 2 people. Nairn GDT, Townsend DF

Keywords: RAFHarvard II,AJ944,41 SFTS,41 Service Flying Training School,Aerodrome,1943-June-16,Nairn,TownsendRCAF L20

Created: 1943-06-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ944>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual night flying circuits & landings

NATURE OF ACCIDENT:

Pupil pilot made one wheel landing,
a/c swung off runway, groundlooped,
causing damage to oleo leg.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Groundloop~~ 2

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

54 w/c Strain.

34

ACTION TAKEN:

Nil